

# EXHIBIT T



# Pole Detail Report



## Location Information

Equip ID:	102292424	Pole Num:	110290307	Map Lat:	38.41032
Map Name:	JJ39	Structure:		Map Lng:	-122.24679
Owner:	PG&E owned pole			Show in Map Guide	
Address:	3683 ATLAS PEAK RD 9S			Show in Google Map	
Cust Info:	VISUAL				
Access:	Readily Accessible			Environmental:	No environmental conditions
Reason:	No Access Issues			Alerts:	No Alerts

Immediate Response Conditions: Immediate Response Comments:

No Immediate Response Conditions

GIS Guid: 1F864A02FE084A9894252714677389E8

## Pole Asset Information

Pole Type:	Through Bore	Location:	Private property	Attachments:	Communications, Distribution
Surface:	Dirt	Walkway:	0	JP Num:	PG110123
Supplier:	McFarland Cascade Co	Mfr Year:	2011	Ins Year:	2011
Species:	Douglas Fir	Class:	4	Height:	45
Orig Treat:	Penta in Petroleum	Orig Circ:	37	Estimated Data:	<input type="checkbox"/>
Existing Rnfcmnt:	No Reinforcement			Solid Surface:	<input type="checkbox"/>

## Inspection History

SIL_C9_041	1 of 3				
Project Status:	ACTIVE	Contractor:	OSM		
Foreman:	m4a0	Current Circ:	37.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	37.00	Front Span Length:	
Crew ID:	OSM241	Encl Pkt Count:		Back Span Length:	
Visit Date:	10/26/2017	Exp Pkt Count:		Full Span Count:	
Work Report:		Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	
Excavation:	No Excavation	No Steel Rsn:		Drop Count:	
External Treat:	No Treat	Banding Issue:		Pole Load:	0%
Internal Test:	Visual Sound and Bore	GL Shell Avg:	99.00	Wood Strength:	100%
Internal Trt:	No Treat	BG Shell Avg:	0.00	Rmng Strength:	0%
Test Issues:	No Issues	Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:	No Issues	Shell @54:	0.00	Comments:	
Pole Top Cndtn:	Fair	Shell @42:	0.00		
Pole Bttm Cndtn:	Penta 10-50 Years	Shell @26:	0.00		
None		Shell @15:	0.00		

SIL_T2_028	2 of 3				
Project Status:	CLOSED	Contractor:	UPT		
Foreman:	cglenn001	Current Circ:	0.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	0.00	Front Span Length:	
Crew ID:	UPT160	Encl Pkt Count:		Back Span Length:	
Visit Date:	10/09/2012	Exp Pkt Count:		Full Span Count:	

Work Report:	943504	Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	
Excavation:	No Excavation	No Steel Rsn:		Drop Count:	
External Treat:	No Treat	Banding Issue:		Pole Load:	0%
Internal Test:	Visual Inspection Only	GL Shell Avg:	0.00	Wood Strength:	100%
Internal Trt:	No Treat	BG Shell Avg:	0.00	Rmng Strength:	0%
Test Issues:	No Issues	Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:	No Issues	Shell @54:	0.00	Comments:	
Pole Top Cndtn:	Fair	Shell @42:	0.00		
Pole Bttm Cndtn:	Fair	Shell @26:	0.00		
None		Shell @15:	0.00		
SIL_T1_062	3 of 3				
Project Status:	CLOSED	Contractor:	DAV		
Foreman:		Current Circ:	44.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	44.00	Front Span Length:	
Crew ID:		Encl Pkt Count:		Back Span Length:	
Visit Date:	06/09/2003	Exp Pkt Count:		Full Span Count:	
Work Report:	PO44122	Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	
Excavation:	Partial Excavation	No Steel Rsn:		Drop Count:	
External Treat:	BG Treat	Banding Issue:		Pole Load:	0%
Internal Test:		GL Shell Avg:	99.00	Wood Strength:	100%
Internal Trt:	Fume	BG Shell Avg:	0.00	Rmng Strength:	0%
Test Issues:		Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:		Shell @54:	0.00	Comments:	
Pole Top Cndtn:		Shell @42:	0.00	04/05/2010 19:51:20 BCH_WM_PTT (BCH_WM_PTT) PCONDBOTXTRA HOLE CHECKS	
Pole Bttm Cndtn:	Fair	Shell @26:	0.00		
Excessive Checking or Cracked		Shell @15:	0.00		